


30 Oct. 1993

Dear Mike:

You probably won't be able to get a 4016 mag; the 4216 or 4316 mags have a fixed dowel to trip the impulse. You will have to remove the key in the shaft, and move the impulse coupling so it will fire at top dead center, when the mag is set to fire at 36 degrees. Then, mark the impulse coupling, and have a new key way cut (electrical discharge machine) in the coupling. This coupling is off the old 0470's engine, which is on the old Bonanza's - right hand turn.

If I can help in any way, just let me know.

Sincerely,



Charles Linn  
P.O. Box 437  
Groveland, CA 95321  
(209) 962-7462

**MAJOR REPAIR AND ALTERATION**  
(Airframe, Powerplant, Propeller, or Appliance)

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form.

|             |   |   |
|-------------|---|---|
| 1. AIRCRAFT | MAKE<br><b>AERONCA</b>  | MODEL<br><b>K</b>   |
|             | SERIAL NO.<br><b>169</b>  | NATIONALITY AND REGISTRATION MARK<br><b>USA N-19301</b>                                   |
| 2. OWNER    | NAME (As shown on registration certificate)<br><b>CHARLES C. LINN</b> | ADDRESS (As shown on registration certificate)<br><b>P.O. BOX 437 GROVELAND, CA 95321</b> |

3. FOR FAA USE ONLY

The data contained herein complies with  
**airworthiness requirements and is approved**  
**only for the above described aircraft, subject**  
**to conformity inspection by a person authorized**  
in FAR 43.7 *[Signature]* Date **02-07-90**

FAA Inspector **WE-FSDO-11**

| 4. UNIT IDENTIFICATION |  |       |            | 5. TYPE |            |
|------------------------|--|-------|------------|---------|------------|
| UNIT                   | MAKE                                       | MODEL | SERIAL NO. | REPAIR  | ALTERATION |
| AIRFRAME               | ***** (As described in item 1 above) ***** |       |            |         | X          |
| POWERPLANT             |  |       |            |         |            |
| PROPELLER              |  |       |            |         |            |
| APPLIANCE              | TYPE                                       |       |            |         |            |
|                        | MANUFACTURER                               |       |            |         |            |

6. CONFORMITY STATEMENT

|  |  |                    |
|--|--|--------------------|
| A. AGENCY'S NAME AND ADDRESS   | B. KIND OF AGENCY  | C. CERTIFICATE NO. |
| <b>Steven D Pinley</b><br><b>PO Box 280</b><br><b>Groveland Ca 95321</b> | <input checked="" type="checkbox"/> U.S. CERTIFICATED MECHANIC | <b>564665307</b>   |
|  | <input type="checkbox"/> FOREIGN CERTIFICATED MECHANIC         |                    |
|  | <input type="checkbox"/> CERTIFICATED REPAIR STATION           |                    |
|  | <input type="checkbox"/> MANUFACTURER                          |                    |

D. I certify that the repair and/or alteration made to the unit(s) identified in item 4 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

|                       |  |
|-----------------------|--|
| DATE<br><b>1-7-90</b> | SIGNATURE OF AUTHORIZED INDIVIDUAL<br><i>Steven D Pinley</i> |
|-----------------------|--|

7. APPROVAL FOR RETURN TO SERVICE

Pursuant to the authority given persons specified below, the unit identified in item 4 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is  APPROVED  REJECTED

|    |                              |                |  |                 |
|----|------------------------------|----------------|--|-----------------|
| BY | FAA FLT. STANDARDS INSPECTOR | MANUFACTURER   | <input checked="" type="checkbox"/> INSPECTION AUTHORIZATION | OTHER (Specify) |
|    | FAA DESIGNEE                 | REPAIR STATION | CANADIAN DEPARTMENT OF TRANSPORT INSPECTOR OF AIRCRAFT       |                 |

|  |  |  |
|--|--|--|
| DATE OF APPROVAL OR REJECTION<br><b>1-7-90</b> | CERTIFICATE OR DESIGNATION NO.<br><b>564665307</b> | SIGNATURE OF AUTHORIZED INDIVIDUAL<br><i>Steven D Pinley</i> |
|--|--|--|

**NOTICE**

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. DESCRIPTION OF WORK ACCOMPLISHED (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

Slick mag R.H. 4016 Ser. No. 5120029 installed. \*\*\*\*\*  
Slick impulse coupling Part No. M2369 installed. \*\*\*\*\*  
Rubber drive parts Part. No. 638172 installed. \*\*\*\*\*

Slick mag 4016 is a four cylinder mag turning crankshaft speed. Aeronca engine drives mag off of the idle gear or crankshaft speed and takes RH turn mag. Four cylinder mag, turning one half speed, fires right sequence for two cylinder engine. If stock mag rotor gear is used, two opposite leads would go to one plug. By extending rotor gear from one pointer to two, 180° apart, this eliminates two wires to one plug and makes a four cylinder mag to a two cylinder mag turning one half speed or crankshaft speed.

Mag impulse set at 25° retarded, turning one half speed is 50° retarded. Set mag for 18° retarded. Aeronca engine runs 36° advanced normally. SEE ATTACHED SHEETS.

USA N-19301 Feb. 5, 1990

\*\*\*\*\*NOTHING MORE FOLLOWS\*\*\*\*\*

ERONCA-K  
MAGNETO CHANGE  
'6 RH MAG INSTALL  
IGN  
INST BY CHARLES CLINN

ADDITIONAL SHEETS ARE ATTACHED

APPROVED BY  
INST BY

